



# GNSS Firmware v5.6.1

---

## Release Notes

**November 2024**

©Copyright Topcon Positioning Systems, Inc. 2024.

All contents in this document are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

# Table of Contents

- SUPPORTED PRODUCTS ..... 3**
  - SYSTEMS ..... 3
  - OEM ..... 3
- ACCOMPANYING TOPCON SOFTWARE AND FIRMWARE..... 3**
- FEATURES AND CHANGES ..... 3**
  - GENERAL ..... 3

## Supported Products

### *Systems*

- Topcon NET-G5, HiPer HR, HiPer VR, MR-2, GR-5<sup>1</sup>
- Sokkia GNR5, GRX3, GCX3

### *OEM*

- Topcon B111, B111A, B125, B210

## Accompanying Topcon Software and Firmware

- To access all new features and improved functionality available in GNSS Firmware 5.5 or later, the following Topcon software versions (or later) are recommended:
  - TRU v3.6.1
  - Topcon Field and Office v9.0
  - Pocket 3D v15.2.3
- BLE Firmware v1.8 (HiPer VR, GRX3)

## Features and Changes

### *General*

- Update to Antenna database
- Update for integrated IMU functionality (HiPer HR, HiPer VR, Sokkia GRX3)
- Operating older GNSS firmware with HIMU rev5.9 will make TILT inoperable. Firmware v5.6.1 is required.

---

<sup>1</sup> GR-5 with Vanguard Technology